

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

Report no:
2134/528/1003

LOCATION DETAILS

Name & address of equipment owner	Location of equipment
CLEAR SOUND PRODUCTIONS LTD UNIT 10 TILEMANS PARK, TILEMANS LANE, SHIPSTON ON SOUR CV36 4PR	


ITEM DETAILS

ID no	JA19362	Asset no		Type of examination	12-monthly periodic visual inspection
SWL	0.5T			Details of tests carried out	None
Description	MANUAL CHAIN HOIST 12MTR H.O.L			Is the equipment safe to operate?	Yes
				Details of any defects & necessary repairs	None.
				Date by which defects must be remedied	
					N/A

First examination before use?	No	Latest date for next examination	06/04/2022
First examination after installation?	No	Date of last examination	19/02/2020
Date of this inspection?	06/04/2021 13:26	Date this report was made	01/09/2021

Authentication Signature:

Authenticator's Name:



K Moore

Inspector's Name:

Kevin Moore

(Lifting equipment engineer for Rigging Services)

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

Report no:
2134/524/1008

LOCATION DETAILS

Name & address of equipment owner	Location of equipment
CLEAR SOUND PRODUCTIONS LTD UNIT 10 TILEMANS PARK, TILEMANS LANE, SHIPSTON ON SOUR CV36 4PR	


ITEM DETAILS

ID no	JA446040	Asset no		Type of examination	12-monthly periodic visual inspection
SWL	0.5T			Details of tests carried out	None
Description	MANUAL CHAIN HOIST 12MTR H.O.L			Is the equipment safe to operate?	Yes
				Details of any defects & necessary repairs	None.
				Date by which defects must be remedied	N/A

First examination before use?	No	Latest date for next examination	06/04/2022
First examination after installation?	No	Date of last examination	19/02/2020
Date of this inspection?	06/04/2021 13:28	Date this report was made	01/09/2021

Authentication Signature:

Authenticator's Name:



K Moore

Inspector's Name:

Kevin Moore

(Lifting equipment engineer for Rigging Services)

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

Report no:
2134/525/1004

LOCATION DETAILS

Name & address of equipment owner	Location of equipment
CLEAR SOUND PRODUCTIONS LTD UNIT 10 TILEMANS PARK, TILEMANS LANE, SHIPSTON ON SOUR CV36 4PR	


ITEM DETAILS

ID no	JA44606	Asset no		Type of examination	12-monthly periodic visual inspection
SWL	0.5T			Details of tests carried out	None
Description	MANUAL CHAIN HOIST 12MTR H.O.L			Is the equipment safe to operate?	Yes
				Details of any defects & necessary repairs	None.
				Date by which defects must be remedied	
					N/A

First examination before use?	No	Latest date for next examination	06/04/2022
First examination after installation?	No	Date of last examination	19/02/2020
Date of this inspection?	06/04/2021 13:26	Date this report was made	01/09/2021

Authentication Signature:

Authenticator's Name:



K Moore

Inspector's Name:

Kevin Moore

(Lifting equipment engineer for Rigging Services)

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

Report no:
2134/521/1001

LOCATION DETAILS

Name & address of equipment owner	Location of equipment
CLEAR SOUND PRODUCTIONS LTD UNIT 10 TILEMANS PARK, TILEMANS LANE, SHIPSTON ON SOUR CV36 4PR	


ITEM DETAILS

ID no	JA44635	Asset no		Type of examination	12-monthly periodic visual inspection
SWL	0.5T			Details of tests carried out	None
Description	MANUAL CHAIN HOIST 12MTR H.O.L			Is the equipment safe to operate?	Yes
				Details of any defects & necessary repairs	None.
				Date by which defects must be remedied	N/A

First examination before use?	No	Latest date for next examination	06/04/2022
First examination after installation?	No	Date of last examination	19/02/2020
Date of this inspection?	06/04/2021 13:26	Date this report was made	01/09/2021

Authentication Signature:

Authenticator's Name:



K Moore

Inspector's Name:

Kevin Moore

(Lifting equipment engineer for Rigging Services)

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

Report no:
2134/526/1002

LOCATION DETAILS

Name & address of equipment owner	Location of equipment
CLEAR SOUND PRODUCTIONS LTD UNIT 10 TILEMANS PARK, TILEMANS LANE, SHIPSTON ON SOUR CV36 4PR	


ITEM DETAILS

ID no	JA45485	Asset no		Type of examination	12-monthly periodic visual inspection
SWL	0.5T			Details of tests carried out	None
Description	MANUAL CHAIN HOIST 12MTR H.O.L			Is the equipment safe to operate?	Yes
				Details of any defects & necessary repairs	None.
				Date by which defects must be remedied	
					N/A

First examination before use?	No	Latest date for next examination	06/04/2022
First examination after installation?	No	Date of last examination	19/02/2020
Date of this inspection?	06/04/2021 13:26	Date this report was made	01/09/2021

Authentication Signature:

Authenticator's Name:



K Moore

Inspector's Name:

Kevin Moore

(Lifting equipment engineer for Rigging Services)

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

Report no:
2134/523/1000

LOCATION DETAILS

Name & address of equipment owner	Location of equipment
CLEAR SOUND PRODUCTIONS LTD UNIT 10 TILEMANS PARK, TILEMANS LANE, SHIPSTON ON SOUR CV36 4PR	


ITEM DETAILS

ID no	T1200475	Asset no		Type of examination	12-monthly periodic visual inspection
SWL	0.5T			Details of tests carried out	None
Description	MANUAL CHAIN HOIST 12MTR H.O.L			Is the equipment safe to operate?	Yes
				Details of any defects & necessary repairs	None.
				Date by which defects must be remedied	N/A

First examination before use?	No	Latest date for next examination	06/04/2022
First examination after installation?	No	Date of last examination	19/02/2020
Date of this inspection?	06/04/2021 13:25	Date this report was made	01/09/2021

Authentication Signature:

Authenticator's Name:



K Moore

Inspector's Name:

Kevin Moore

(Lifting equipment engineer for Rigging Services)

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

Report no:
2134/518/1005

LOCATION DETAILS

Name & address of equipment owner	Location of equipment
CLEAR SOUND PRODUCTIONS LTD UNIT 10 TILEMANS PARK, TILEMANS LANE, SHIPSTON ON SOUR CV36 4PR	


ITEM DETAILS

ID no	T1200476	Asset no		Type of examination	12-monthly periodic visual inspection
SWL	0.5T			Details of tests carried out	None
Description	MANUAL CHAIN HOIST 12MTR H.O.L			Is the equipment safe to operate?	Yes
				Details of any defects & necessary repairs	None.
				Date by which defects must be remedied	N/A

First examination before use?	No	Latest date for next examination	06/04/2022
First examination after installation?	No	Date of last examination	19/02/2020
Date of this inspection?	06/04/2021 13:26	Date this report was made	01/09/2021

Authentication Signature:

Authenticator's Name:



K Moore

Inspector's Name:

Kevin Moore

(Lifting equipment engineer for Rigging Services)

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

Report no:
2134/527/998

LOCATION DETAILS

Name & address of equipment owner	Location of equipment
CLEAR SOUND PRODUCTIONS LTD UNIT 10 TILEMANS PARK, TILEMANS LANE, SHIPSTON ON SOUR CV36 4PR	


ITEM DETAILS

ID no	T1200511	Asset no		Type of examination	12-monthly periodic visual inspection
SWL	0.5T			Details of tests carried out	None
Description	MANUAL CHAIN HOIST 12MTR H.O.L			Is the equipment safe to operate?	Yes
				Details of any defects & necessary repairs	None.
				Date by which defects must be remedied	N/A

First examination before use?	No	Latest date for next examination	06/04/2022
First examination after installation?	No	Date of last examination	19/02/2020
Date of this inspection?	06/04/2021 13:25	Date this report was made	01/09/2021

Authentication Signature:

Authenticator's Name:



K Moore

Inspector's Name:

Kevin Moore

(Lifting equipment engineer for Rigging Services)

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

Report no:
2134/522/999

LOCATION DETAILS

Name & address of equipment owner	Location of equipment
CLEAR SOUND PRODUCTIONS LTD UNIT 10 TILEMANS PARK, TILEMANS LANE, SHIPSTON ON SOUR CV36 4PR	


ITEM DETAILS

ID no	T1200512	Asset no		Type of examination	12-monthly periodic visual inspection
SWL	0.5T			Details of tests carried out	None
Description	MANUAL CHAIN HOIST 12MTR H.O.L			Is the equipment safe to operate?	Yes
				Details of any defects & necessary repairs	None.
				Date by which defects must be remedied	N/A

First examination before use?	No	Latest date for next examination	06/04/2022
First examination after installation?	No	Date of last examination	19/02/2020
Date of this inspection?	06/04/2021 13:25	Date this report was made	01/09/2021

Authentication Signature:

Authenticator's Name:



K Moore

Inspector's Name:

Kevin Moore

(Lifting equipment engineer for Rigging Services)

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

Report no:
2134/519/1007

LOCATION DETAILS

Name & address of equipment owner	Location of equipment
CLEAR SOUND PRODUCTIONS LTD UNIT 10 TILEMANS PARK, TILEMANS LANE, SHIPSTON ON SOUR CV36 4PR	


ITEM DETAILS

ID no	T18080091	Asset no		Type of examination	12-monthly periodic visual inspection
SWL	0.5T			Details of tests carried out	None
Description	MANUAL CHAIN HOIST 12MTR H.O.L			Is the equipment safe to operate?	Yes
				Details of any defects & necessary repairs	None.
				Date by which defects must be remedied	N/A

First examination before use?	No	Latest date for next examination	06/04/2022
First examination after installation?	No	Date of last examination	19/02/2020
Date of this inspection?	06/04/2021 13:27	Date this report was made	01/09/2021

Authentication Signature:

Authenticator's Name:



K Moore

Inspector's Name:

Kevin Moore

(Lifting equipment engineer for Rigging Services)

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

Report no:
2134/520/1006

LOCATION DETAILS

Name & address of equipment owner	Location of equipment
CLEAR SOUND PRODUCTIONS LTD UNIT 10 TILEMANS PARK, TILEMANS LANE, SHIPSTON ON SOUR CV36 4PR	


ITEM DETAILS

ID no	T18080114	Asset no		Type of examination	12-monthly periodic visual inspection
SWL	0.5T			Details of tests carried out	None
Description	MANUAL CHAIN HOIST 12MTR H.O.L			Is the equipment safe to operate?	Yes
				Details of any defects & necessary repairs	None.
				Date by which defects must be remedied	
					N/A

First examination before use?	No	Latest date for next examination	06/04/2022
First examination after installation?	No	Date of last examination	19/02/2020
Date of this inspection?	06/04/2021 13:27	Date this report was made	01/09/2021

Authentication Signature:

Authenticator's Name:



K Moore

Inspector's Name:

Kevin Moore

(Lifting equipment engineer for Rigging Services)